



F16.3D





Start Providing at least one encapsulating ~605 Applying the encopsulating transport to the layer. Removal of the layer from the substrate surface ~6/5 END F16.6